DART SERVICE INSTRUCTION

TO AMEND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D205-634 Rev. 3

REF. CANADIAN STC: SH96-88 REF. FAA STC: SR00563NY REF. EASA STC: EASA.IM.R.S.01303

PURPOSE:

The parts list of Instructions for Continued Airworthiness ICA-D205-634 Rev. 3 lists the incorrect washer for the D3407-041 Tow Ring Assembly. The correct washer is the D3417-5 Washer, which has a groove to fit the ridge on the sides of the Dart skidtube.

CHANGE:

The parts in section 32.9 (pg. 35) of ICA-D205-634 Rev. 3 is amended as follows:

ITEM	634 -011	634 -015	634 -041	634 -045	641 -011	PART NUMBER	DESCRIPTION		
	X					D205-634-011	SKIDTUBE INSTALLATION, (STANDARD)		
		Х				D205-634-015	SKIDTUBE INSTALLATION, (MODIFIED)		
IS:							1		
44	2	2				D3417-5	WASHER		
	<u> </u>								
WAS:	:								
•									
44	2	2				D3417-3	WASHER		
	L								

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

BY: D. SHEPHERD (DE # 02)

DATE: 09.06.30
CERT. NO.: SH96-88
ISSUE NO.: 3

Α	NEW ISSUE , REF	СР	09.06.30			
REV.		DESCRIPTION	BY	DATE		
DESIGN	P.	DART AEROSP	ACE	CE LTD		
DRAWN	98	HAWKESBURY, ONTARIO, CANADA				
CHECKE	ED J	DRAWING NO.		REV. A		
MFG. AF	PR. N/A	DSI 9468	5	SHEET 1 OF 1		
APPRO\	/ED	TITLE		SCALE		
DE APP	₹ #	PARTS LIST CORRECTION		NTS		
DATE	09.06.30	COPYRIGHT © 2009 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITEN PERMISSION FROM DART AEROSPACE LTD.				